

Safety Verification under ROGS – Southend Pier New train introduction



Southend Pier Railway has procured two new battery trains.

Replace existing diesel trains which date from 1986.

I am acting as Independent Competent Person to complete the Safety Verification process under ROGS.






The introduction of new rolling stock can lead to **new or altered risks**.

SPR is listed as a **non-mainline** Transport Undertaking (TU) on the ORR exclusion list.

SPR is listed as a 'lower-risk TU' in ROGS because it does not run at speeds above 40 kilometres per hour. A low-risk TU must still have a written SMS.

A low-risk TU introducing new vehicles must have a safety verification process, involving an independent competent person.





Southend Pier extends 2.16km into the Thames Estuary 3 ft gauge railway operates almost the full pier length Stations at shore (North) and pier head (South) ends of pier Single track, passing loop in middle Carries passengers, oversize loads, staff and goods Two trains supplied by Severn Lamb, each 6 cars, 51.5m in length



- Designed for maritime environmental conditions
- Capacity 208 passengers
- 12 wheelchair spaces per train
- Restricted loading gauge
- 2 double-doors per side per car (24 door sets total)
- 2-axle roller-shutter bin wagon on each train



- New trains meet RVAR with exemptions
- Appearance in keeping with Victorian aesthetic of pier



Operation of new trains

- Seasonal operation
- Clock face timetable
- Up to 18 return trips per day per train in peak season
- Two train operation in peak season
- Recharge overnight
- Themed events LEDs
- Line of sight control fitted with slow down & stop system





ICP must be appointed early in the project. To consider design, set standards, provide assurance that inspection and assessment plan are enacted safely.

ICP does not duplicate the functions / activities of the project team.

ICP reviews the design, build, testing, commissioning and entry into service of the rolling stock.


Witness testing and reviews changes to SMS.



Examples of risks introduced by the new trains (1)

Batteries and battery charging arrangements

Train geometry different to earlier trains



View of battery compartment with Li-ion battery pack highlighted (blue)






and SMS

Examples of risks introduced by the new trains (2) Revised operating procedures Pc

Point motor cover out of gauge to new train

	Bisk Assessment	Sheet			0
Description			Risk Matrix		
longitudinally spanning a maximum section hardwood fining/bearsr, whi span between the middle two long to further renewal/replacement has tai	he plor situations is formed of 200mm x 75mm sections of 1.5m, where it as (fixed to by 2 na, coach arrest in turns belief to a vice the norm x 150mm Roved Section 1 and the section of the main pler structure. This decking the place in a small arree at the North Station in 135 events of some bearers in the Passing Loop area ((c) on a 100mm x 50m (c) Joist (RSJ) The F (was all replaced in 1 (c) and the entire South (c) and the entire South)	ISJ's 986 and 5 Station	Seventy 1 2 3 Atlingeopus 4	4 5
	Hazards/Risks			5	
A common failure of this type of decking, system is the deterioration of the bearers and the ends of the planke due to surface water atting in the fixing recesses and panetrating the exposed and grain of the timber. Failure of this type would result in movement of the track as the traine pass over.				No Action	
				Action Required	
continue to barrentes to demonstrate	one weiking the cask for inspeacedmand maniter	ance reasons.		Seve	rity
. exercises of the second second basis	nie keining me bauk für inspeatuori and maniter	ance reasons.		Seve 1 Negligat 2 Margina 3 Moderat	ole A
a summer of horizon of simulations	Existing Mitigating Actions	ance reasons.		1 Negligat 2 Margina	ole A
Failures of this type are far less comm	Existing Mitigating Actions	e to the fact that hea		1 Negligat 2 Margina 3 Moderat 4 Critical 5 Catastro	ole i te ophic
Failures of this type are far less commission of the air could	Existing Mitigating Actions	e to the fact that hea		1 Negligat 2 Margina 3 Moderat 4 Critical 5 Catastri Probe	ole i te ophic ability
Feilures of this type are far less comm locomotives engines and the air cools water laying in the recesses , every to	Existing Mitigating Actions	e to the fact that hea		1 Negligat 2 Margina 3 Moderal 4 Critical 5 Catastro Probe 1 Unlikely	ole i te ophic ability y
Feilures of this type are far less comm locomotives engines and the air cools water laying in the recesses , every to	Existing Mitigating Actions	e to the fact that hea		1 Negligat 2 Margina 3 Moderal 4 Critical 5 Catastro Probe 1 Unlikely 2 Seldon	ole i cophic a bility y n
Failures of this type are far less comm	Existing Mitigating Actions	e to the fact that hea		1 Negligat 2 Margina 3 Moderat 4 Criticat 5 Catastric Probe 1 Unikel 2 Seldon 3 Occasi	ole i cophic a bility y n
Feilures of this type are far less comm locomotives engines and the air cools water laying in the recesses , every to	Existing Mitigating Actions ron than on the adjacent pedestrian walkway du gsystem used act as a semi-drying system red methe trains pass over.	e to the fact that hes using the emount of		1 Negligat 2 Margina 3 Moderat 4 Critical 5 Catastric Probe 1 Unikeli 2 Seldon 3 Occasi 4 Likely	ole ite ophia a bility y n ianal
Feilures of this type are far less comm locomotives engines and the air cools water laying in the recesses , every to	Existing Mitigating Actions from the adjacent pedestrian walkway du ng system used act as a semi-drying system red methe trains pass over.	e to the fact that hes ucing the emount of 2		1 Negligat 2 Margina 3 Moderat 4 Critical 5 Catastin Probe 1 Unikely 2 Seidon 3 Occasi 4 Ukely 5 Freque	ole ite ophia ability y n ianal
Failures of this type are far less comm locomotives engines and the air could water laying in the recesses , every th infrequently recoreded inspections	Existing Mitigating Actions ron than on the adjacent pedestrian walkway du gsystem used act as a semi-drying system red methe trains pass over.	e to the fact that hes using the emount of		1 Negligat 2 Margina 3 Moderat 4 Critical 5 Catastin Probe 1 Unitely 2 Seldon 3 Occasi 4 Ukely 5 Freque Date	ole ite ability y ional ent Oct 09
Feilures of this type are far less comm locomotives engines and the air cools water laying in the recesses , every to	Existing Mitigating Actions from the adjacent pedestrian walkway du ng system used act as a semi-drying system red methe trains pass over.	e to the fact that hes ucing the emount of 2		1 Negligat 2 Margina 3 Moderal 4 Critical 5 Catastri Probe 1 Unikely 2 Seidon 3 Occasi 4 Ukely 5 Freque Date By	ole ite ophia ability y n ianal





If you are

- A non-mainline Transport Undertaking
- Deemed as lower-risk by DfT/ORR

And

- You are introducing new or significantly altered Rolling Stock or Infrastructure
- You must appoint an Independent Competent Person to complete Safety Verification.
- You are in breach of your **legal obligations** otherwise.





Q & A

Hugh O'Neill Managing Consultant Frazer-Nash Consultancy

Please come see us at the Frazer-Nash stand in the exhibition hall